Energy performance certificate (EPC)

| 5, Lollard Croft COVENTRY CV3 5GH | Energy rating | Valid until: Certificate number: | 20 November 2028 8638-7929-5509-7540-9922 |
|---|---------------|--|--|
| Property type | | | |
| Mid-terrace house | | | |

Total floor area

77 square metres

Rules on letting this property

Properties can be rented if they have an energy rating from A to E.

If the property is rated F or G, it cannot be let, unless an exemption has been registered. You can read <u>guidance for landlords</u> <u>on the regulations and exemptions (https://www.gov.uk/guidance/domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance)</u>.

Energy efficiency rating for this property

This property's current energy rating is C. It has the potential to be B.

See how to improve this property's energy performance.

| Score | Energy rating | Current | Potential |
|-------|---------------|---------------|---------------|
| 92+ | Α | | |
| 81-91 | B | | 86 B |
| 69-80 | С | 69 c | |
| 55-68 | D | | |
| 39-54 | E | | |
| 21-38 | F | | |
| 1-20 | | G | |

The graph shows this property's current and potential energy efficiency.

Properties are given a rating from A (most efficient) to G (least efficient).

Properties are also given a score. The higher the number the lower your fuel bills are likely to be.

For properties in England and Wales:

- the average energy rating is D
- the average energy score is 60

Breakdown of property's energy performance

This section shows the energy performance for features of this property. The assessment does not consider the condition of a feature and how well it is working.

Each feature is assessed as one of the following:

- very good (most efficient)
- good
- average
- poor
- very poor (least efficient)

When the description says "assumed", it means that the feature could not be inspected and an assumption has been made based on the property's age and type.

| Feature | Description | Rating |
|---------|--|-----------|
| Wall | Cavity wall, as built, no insulation (assumed) | Poor |
| Roof | Pitched, 300 mm loft insulation | Very good |
| Window | Fully double glazed | Average |

https://find-energy-certificate.service.gov.uk/energy-certificate/8638-7929-5509-7540-9922

6/15/22, 6:55 AM

Energy performance certificate (EPC) – Find an energy certificate – GOV.UK

| Feature | Description | Rating |
|----------------------|--|-----------|
| Main heating | Boiler and radiators, mains gas | Good |
| Main heating control | Programmer, room thermostat and TRVs | Good |
| Hot water | From main system | Good |
| Lighting | Low energy lighting in all fixed outlets | Very good |
| Floor | Suspended, no insulation (assumed) | N/A |
| Secondary heating | None | N/A |

Primary energy use

The primary energy use for this property per year is 216 kilowatt hours per square metre (kWh/m2).

What is primary energy use?

Additional information

Additional information about this property:

• Cavity fill is recommended

Environmental impact of this property

This property's current environmental impact rating is D. It has the potential to be B.

Properties are rated in a scale from A to G based on how much carbon dioxide (CO2) they produce.

Properties with an A rating produce less CO2 than G rated properties.

An average household produces

6 tonnes of CO2

This property produces

2.9 tonnes of CO2

This property's potential production

1.3 tonnes of CO2

By making the <u>recommended changes</u>, you could reduce this property's CO2 emissions by 1.6 tonnes per year. This will help to protect the environment.

Environmental impact ratings are based on assumptions about average occupancy and energy use. They may not reflect how energy is consumed by the people living at the property.

Improve this property's energy performance

By following our step by step recommendations you could reduce this property's energy use and potentially save money.

Carrying out these changes in order will improve the property's energy rating and score from C (69) to B (86).

Do I need to follow these steps in order?

Step 1: Cavity wall insulation

Cavity wall insulation

Typical installation cost

Typical yearly saving

Potential rating after completing step 1

Floor insulation (suspended floor)

Typical yearly saving

Potential rating after completing steps 1 and 2

Step 3: Solar water heating

Solar water heating

Typical installation cost

£4,000 - £6,000

Potential energy

rating

£500 - £1,500

£71


72 | C

£800 - £1,200

£35

74 | C

Typical yearly saving



The estimated cost shows how much the average household would spend in this property for heating, lighting and hot water. It is not based on how energy is used by the people living at the property.

The potential saving shows how much money you could save if you complete each recommended step in order.

For advice on how to reduce your energy bills visit Simple Energy Advice (https://www.simpleenergyadvice.org.uk/).

Heating use in this property

Heating a property usually makes up the majority of energy costs.

Estimated energy used to heat this property

| Type of heating | Estimated energy used | |
|---|------------------------|--|
| Space heating | 9201 kWh per year | |
| Water heating | 1893 kWh per year | |
| Potential energy savings by installing insulation | | |
| Type of insulation | Amount of energy saved | |

Cavity wall insulation

1618 kWh per year

Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

Assessor contact details

Assessor's name

Alexander Close

Telephone

07450208253

Email

alexclose.cov@gmail.com

Accreditation scheme contact details

Accreditation scheme

Stroma Certification Ltd

Assessor ID

STRO015226

Telephone

0330 124 9660

Email

certification@stroma.com

Assessment details

Assessor's declaration

No related party

Date of assessment

20 November 2018

Date of certificate

21 November 2018

Type of assessment

RdSAP

Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <u>dluhc.digital-services@levellingup.gov.uk</u> or call our helpdesk on 020 3829 0748.

Certificate number

2858-3059-7209-5858-9974 (/energy-certificate/2858-3059-7209-5858-9974)

Valid until

24 January 2028